

AUDIO CODEC - ALC861-VD

In order to avoid incorrect JD recognition, all of JD resistors should be placed as close as possible to the sense pin of codec.

